

Product Change Notification

※PCN Release Date:

02, 21, 2023

※PCN Number:

PCN2023022106 (P230057)

※Change Title:

BOM is changed for IMB-1212 and IMB-1213

※To Be Changed:

PCB BIOS BOM Other :

※Change Method:

Running Change

※Description of Change:

1. Remove MLCC 1UF/16V(0603)X7R 10% (P/N: 11G233110511030) from location PC21.
2. Remove MLCC 0.1UF/16V(0402)X7R 10% (P/N: 11G232110411030) from location AC2.
3. Add MLCC 0.047UF/50V (0402)X7R 10% (P/N: 11G232147314030) to location AC2.
4. Remove MLCC 1UF/6.3V (0402) X5R 10% (P/N: 11G232210515030) from location C43.
5. Add MLCC 0.047UF/50V (0402)X7R 10% (P/N: 11G232147314030) to location C43.

※Model List:

| Model Name | PCB Rev. |
|------------|----------|
| IMB-1212 | R1.03 |
| IMB-1213 | R1.03 |