

Product Change Notification

| ※PCN | Dal | 0000 | Data |
|-------------|-----|-------|-------|
| ** PUN | Rei | lease | Date: |

07, 31, 2024

※PCN Number:

PCN2024073112 (P240379)

%Change Title:

BOM is changed for IMB-1234 series

X To Be Changed:

[]PCB []BIOS [V]BOM []Other:

X Change Method:

Running change.

X Impact of change

| Item | Impact |
|----------------------------------|--------|
| Impact on Mechanical Design | No |
| Impact on Software Compatibility | No |
| Impact on Board Certifications | No |
| Physical Outlook Change | No |
| Ordering P/N Change | No |

Description of Change:

- 1. Remove C.S SLB9670VQ2.0 PG-VQFN-32-13 TPM2.0 FW:7.85 (P/N: 02G851000D40AK) from location TPMS_1.
- 2. Add C.S SLB9672VU2.0 PG-UQFN32-1-2 TPM2.0 FW:15.23 (P/N: 02G851000E10AK) to location TPMS 1.

***Model List:**

| Model Name | PCB Rev. |
|------------|----------|
| IMB-1234P | R1.02 |
| IMB-1234M | R1.02 |
| IMB-1234V | R1.02 |