

Product Change Notification

※PCN Release Date:

08, 02, 2024

※PCN Number:

PCN2024080203 (P240396)

※Change Title:

BOM is changed for IMB-1232-WV, IMB-1233-WV, and IMB-X1233-WV

※To Be Changed:

PCB BIOS BOM Other :

※Change Method:

Running change.

※Impact of change

| Item | Impact |
|----------------------------------|--------|
| Impact on Mechanical Design | No |
| Impact on Software Compatibility | No |
| Impact on Board Certifications | No |
| Physical Outlook Change | No |
| Ordering P/N Change | No |

※Description of Change:

1. Remove C.S SLB9670VQ2.0 PG-VQFN-32-13 TPM2.0 FW:7.85 (P/N: 02G851000D40AK) from location TPMS_1.
2. Add C.S SLB9672VU2.0 PG-UQFN32-1-2 TPM2.0 FW:15.23 (P/N: 02G851000E10AK) to location TPMS_1.

※Model List:

| Model Name | PCB Rev. |
|--------------|----------|
| IMB-1232-WV | R1.03 |
| IMB-1233-WV | R1.03 |
| IMB-X1233-WV | R1.03 |