

Product Change Notification

| ≫PCN | | | Data. |
|-------------|----|-------|-------|
| •ו PUIN | RE | iease | Date: |

01, 04, 2024

※PCN Number:

PCN2024010406 (P230514 & PP230090)

****Change Title:**

BOM is changed for IMB-X1220-L, IMB-1220-L, IMB-1220-D, IMB-1221-L, and IMB-1221-D

X To Be Changed:

[]PCB []BIOS [V]BOM []Other:

X Change Method:

Running Change

X Impact of change

| Item | Impact |
|----------------------------------|--------|
| Impact on Mechanical Design | No |
| Impact on Software Compatibility | No |
| Impact on Board Certifications | No |
| Physical Outlook Change | No |
| Ordering P/N Change | No |

Description of Change:

To enhance compatibility, we removed M.2 Key E and M.2 Key M SMBus function.

1. Remove DUAL N-MOSFET SM1600DSCSC-TRG (P/N: 07G005158010AK) from location M2EQ1, M2EQ2.

※Model List:

| Model Name | PCB Rev. |
|-------------|----------|
| IMB-X1220-L | R1.04A |
| IMB-1220-L | R1.04A |
| IMB-1220-D | R1.04A |
| IMB-1221-L | R1.04A |
| IMB-1221-D | R1.04A |