

Product Change Notification

01, 04, 2024

***PCN Number:**

PCN2024010407 (P230529)

※Change Title:

BOM is changed for IMB-1222, IMB-1222-WV, IMB-1223, IMB-1223-WV, and IMB-X1222

X To Be Changed:

[]PCB []BIOS [V]BOM []Other:

X Change Method:

Running Change

X Impact of change

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Board Certifications	No
Physical Outlook Change	No
Ordering P/N Change	No

Description of Change:

To enhance compatibility, we removed M.2 Key E and M.2 Key M SMBus function.

- 1. Remove DUAL N-MOSFET SM1600DSCSC-TRG (P/N: 07G005158010AK) from location SQ2, SQ3.
- 2. Remove RES 2.2K OHM 1/16W (0402) 1% (P/N: 10G212220114010) from location SR50, SR51, SR53, SR54.

***Model List:**

Model Name	PCB Rev.
IMB-1222	R1.04B
IMB-1222-WV	R1.04B
IMB-1223	R1.04B
IMB-1223-WV	R1.04B
IMB-X1222	R1.04B