

## **Product Change Notification**

**\*PCN** Release Date:

07, 31, 2024

**\*PCN Number:** 

PCN2024073103 (P240366)

**%Change Title:** 

BOM is changed for SBC-370 and SBC-371 series

**X** To Be Changed:

[ ]PCB [ ]BIOS [ V ]BOM [ ]Other:

**X** Change Method:

Running change.

**X** Impact of change

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Board Certifications	No
Physical Outlook Change	No
Ordering P/N Change	No

## Description of Change:

- 1. Remove C.S SLB9670VQ2.0 PG-VQFN-32-13 TPM2.0 FW:7.85 (P/N: 02G851000D40AK) from location U31.
- 2. Add C.S SLB9672VU2.0 PG-UQFN32-1-2 TPM2.0 FW:15.23 (P/N: 02G851000E10AK) to location U31.

## **※Model List:**

Model Name	PCB Rev.	Model Name	PCB Rev.
SBC-370P	R1.02	SBC-371P	R1.02
SBC-370M	R1.02	SBC-371M	R1.02
SBC-370V	R1.02	SBC-371V	R1.02