

# Product Change Notification

**※PCN Release Date:**

07, 31, 2024

**※PCN Number:**

PCN2024073107 (P240372)

**※Change Title:**

BOM is changed for IMB-1222, IMB-1222-WV and IMB-X1222-WV

**※To Be Changed:**

PCB  BIOS  BOM  Other :

**※Change Method:**

Running change.

**※Impact of change**

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Board Certifications	No
Physical Outlook Change	No
Ordering P/N Change	No

**※Description of Change:**

1. Remove C.S SLB9670VQ2.0 PG-VQFN-32-13 TPM2.0 FW:7.85 (P/N: 02G851000D40AK) from location TPMS\_1.
2. Add C.S SLB9672VU2.0 PG-UQFN32-1-2 TPM2.0 FW:15.23 (P/N: 02G851000E10AK) to location TPMS\_1.

**※Model List:**

Model Name	PCB Rev.
IMB-1222	R1.04B
IMB-1222-WV	R1.04B
IMB-X1222-WV	R1.04B