

# **Product Change Notification**

| <b>※PCN</b> | Dal | 0000  | Data  |
|-------------|-----|-------|-------|
| ** PUN      | Rei | lease | Date: |

07, 31, 2024

#### **\*PCN Number:**

PCN2024073118 (P240369)

#### **\*Change Title:**

BOM is changed for NUC-N97 series

### **X** To Be Changed:

[ ]PCB [ ]BIOS [ V ]BOM [ ]Other:

## **X** Change Method:

Running change.

**X** Impact of change

| Item                             | Impact |
|----------------------------------|--------|
| Impact on Mechanical Design      | No     |
| Impact on Software Compatibility | No     |
| Impact on Board Certifications   | No     |
| Physical Outlook Change          | No     |
| Ordering P/N Change              | No     |

## Description of Change:

- 1. Remove C.S SLB9670VQ2.0 PG-VQFN-32-13 TPM2.0 FW:7.85 (P/N: 02G851000D40AK) from location U12.
- 2. Add C.S SLB9672VU2.0 PG-UQFN32-1-2 TPM2.0 FW:15.23 (P/N: 02G851000E10AK) to location U12.

#### **\*Model List:**

| Model Name | PCB Rev. | PCB Rev. | Model Name  | Model Name |
|------------|----------|----------|-------------|------------|
| NUC-N97    | R1.01    | R1.02    | NUC BOX-N97 | iBOX-N97   |