

# Product Change Notification

**※PCN Release Date:**

08, 02, 2024

**※PCN Number:**

PCN2024080201 (P240392)

**※Change Title:**

BOM is changed for IMB-1211-L and IMB-1211-D

**※To Be Changed:**

PCB     BIOS     BOM     Other :

**※Change Method:**

Running change.

**※Impact of change**

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Board Certifications	No
Physical Outlook Change	No
Ordering P/N Change	No

**※Description of Change:**

1. Remove C.S SLB9670VQ2.0 PG-VQFN-32-13 TPM2.0 FW:7.85 (P/N: 02G851000D40AK) from location TPMS\_1.
2. Add C.S SLB9672VU2.0 PG-UQFN32-1-2 TPM2.0 FW:15.23 (P/N: 02G851000E10AK) to location TPMS\_1.

**※Model List:**

Model Name	PCB Rev.
IMB-1211-L	R1.04
IMB-1211-D	R1.04